

SDMS US EPA REGION V

COLOR - RESOLUTION - 3

IMAGERY INSERT FORM

Multiple pages of this document include color or resolution variations and may be illegible in SDMS due to bad source documents. Unless otherwise noted, these pages are available in monochrome. (The source document page(s) are more legible than the images.) The original document is available for viewing at the Superfund Records Center.

SITE NAME	SAUGET AREA 11
DOC ID #	150769
DOCUMENT VARIATION	___ COLOR OR <u>X</u> RESOLUTION
PRP	RMD - SAUGET AREA II
PHASE	SID
OPERABLE UNITS	
LOCATION	Box #__ Folder #__ Subsection__
PHASE (AR DOCUMENTS ONLY)	___ Remedial ___ Removal ___ Deletion Docket ___ ___ Original ___ Update # ___ Volume ___ of ___
COMMENT(S) XEROX COPY OF SITE PHOTOGRAPHS REF. #13	

150769


SAUGET AREA 2
ILD000605790Reference No. 13

SITE NAME: Sauget Area II Sites


SITE ILB: 000605790

COUNTY: St. Clair

DATE: after 1993 flood
TIME:
PHOTO BY: IEPA Personnel
ROLL / PHOTO: photo 1
SAMPLE:
DIRECTION: NW
COMMENTS:
Sample taken from south end of
site "R" facing northwest.
Photo shows waste and debris
along Mississippi River bank &
floodplain



DATE: after 1993 flood
TIME:
PHOTO BY: IEPA Personnel
ROLL / PHOTO: photo 2
SAMPLE:
DIRECTION: NW
COMMENTS:
Photo taken from approx 20 feet
west-northwest of photo #1
Debris exposed after the flood.



SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 3


SAMPLE:

DIRECTION: NW

COMMENTS:

Photo taken from approx 20 feet
west-southwest of photo #1

Debris exposed after the flood.



DATE: after 1993 flood

TIME: 1045

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 4


SAMPLE:

DIRECTION: South

COMMENTS:

Photo taken along Mississippi
River at south end of Site "Q".

NOTE: discolored seeps from
debris piles



SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 5

SAMPLE:

DIRECTION: South

COMMENTS:

Photo taken along Mississippi

River at south end of Site "Q".

NOTE: discolored seeps from
debris piles



DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 6

SAMPLE:


DIRECTION: W

COMMENTS:

Photo taken along Mississippi

River at south end of Site "Q".

Close-up of discolored seep



SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel


ROLL / PHOTO : photo 7

SAMPLE:

DIRECTION: NW

COMMENTS:

Photo of Mississippi River &
St. Louis area.



DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel


ROLL / PHOTO: photo 8

SAMPLE:

DIRECTION: W

COMMENTS:

Photo shows seeps entering
Mississippi River



SITE NAME: Sauget Area II Sites

SITE ILD: 000605790

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 9

SAMPLE:

DIRECTION: N

COMMENTS:

Photo taken from south end of

Site "Q".

NOTE: backhoe at removal area



DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 10

SAMPLE:

DIRECTION: West


COMMENTS:

Photo taken from south end of

Site "Q".

identifies seeps flowing into

river



SITE NAME: Sauget Area II Sites

SITE ILD: 00000021

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel


ROLL / PHOTO: photo 11

SAMPLE:

DIRECTION: West

COMMENTS:

See photo # 10



DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel


ROLL / PHOTO: photo 12

SAMPLE:

DIRECTION: West

COMMENTS:

See photo #s 10 & 11



SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 13

SAMPLE:

DIRECTION: NW

COMMENTS:

Photo is close-up of photo #s

10 - 12. White stake at center

left is in all 4 photos.

NOTE: discolored seeps



DATE:

TIME:

PHOTO BY:

ROLL / PHOTO:

SAMPLE:

DIRECTION:

COMMENTS:

NO PHOTO TAKEN

SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: 9/2/93 end of 1993 flood

TIME: 12:25

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 1

SAMPLE: X102

DIRECTION:

COMMENTS:

Photo of sample X102

ite SAUGET II-O
ate 9-2-93 Time 12:25
sample X102
Depth ON SURFACE
3 ft

DATE: 9/2/93 end of 1993 flood

TIME: 3:35

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 3

SAMPLE:

DIRECTION: South

COMMENTS:

Photo taken along floodplain/bank
of Mississippi River.

Flood waters still receding

St. Louis Arch is in upper right.



SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: during 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 1 & 2

SAMPLE: Panorama

DIRECTION: West

North is up, east is to right

Sample taken from north of

sites "Q" & "R" facing west during

high flood stage.

Photo taken from on levee. Large

building in center of photo is

located EAST of river. River is

behind building.

DATE:

TIME:

PHOTO BY:

ROLL / PHOTO:

SAMPLE:

DIRECTION:

COMMENTS:

See above



SITE NAME: Sauget Area II Sites

SITE ILB: 000605790

COUNTY: St. Clair

DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 1

SAMPLE:

DIRECTION: east

COMMENTS:

Photo taken along Mississippi

River bank near center of Site "Q".

Drums exposed after 1993 flood.



DATE: after 1993 flood

TIME:

PHOTO BY: IEPA Personnel

ROLL / PHOTO: photo 2

SAMPLE:

DIRECTION: W

COMMENTS:

Photo taken along Mississippi

River bank near center of Site "Q".

Drums exposed after 1993 flood.

